

SAFETY ALERT

DATE: 17 June 2022

Worker burnt during hot work

This safety alert provides safety advice for the NSW mining industry.

Issue


A boilermaker suffered burns to the right-hand side of their face as a consequence of the ignition of an unidentified flammable substance.

Circumstances

On Tuesday 7 June 2022, a boilermaker was preparing to replace a 30 mm diameter plug in the top of the LHS boom pivot pin housing/boss on a Caterpillar 6050 face shovel.

While striking an arc on a test piece adjacent to the access hole cut into the superstructure void, a flammable substance ignited, burning the boilermaker's face.

Figure 1: Hot work location



Investigation

The NSW Resources Regulator has conducted a site assessment to obtain information about the event. An initial assessment has identified that the superstructure void, that the repair was being conducted in, had not been adequately ventilated or purged to remove ignition sources throughout the repair.

Work leading up to the incident included LPG/oxy cutting, air arc gouging, surface cleaning using degreaser, contact cleaner aerosols, preheating with LPG gas heater, and rotary burr grinding in the superstructure void.

In preparation for welding the plug, the boilermaker was undertaking a test weld on a metal plate outside of the superstructure when the flame event happened.

Figure 2: Superstructure void and test piece adjacent to access hole.



Recommendations

Mine operators should:

- Carry out a risk assessment regarding hot work activities undertaken onsite in/into voids and confined spaces. The risk assessment should take into consideration:
 - contaminated atmospheres and surfaces
 - the generation of combustible gases through gas cutting heating or welding
 - changing internal atmosphere through application of cleaning fluids (degreasers)
 - ventilation and gas monitoring requirements

- the use of inert gas to purge spaces
- Implement controls from the risk assessment.

A task-based risk assessment or JHA should be conducted prior to the commencement of any hot work activities in/into voids or confined spaces.

NOTE: Please ensure all relevant people in your organisation receive a copy of this safety alert and are informed of its content and recommendations. This safety alert should be processed in a systematic manner through the mine's information and communication process. It should also be placed on the mine's common area, such as your notice board where appropriate.

Visit our [website](#) to:

- find more safety alerts and bulletins
- use our searchable safety database

Other relevant resources

- [NSW Government code of practice welding processes](#)
- [NSW Government code of practice confined spaces](#)
- [Resources Regulator – Technical reference guide – Hot Work \(Cutting and Welding\)](#)
- [SA15-01 Fire ignites after worker drills into a sealed void](#)
- [SA03-08 Explosive conditions: Pre-heating on confined space prior to welding](#)

© State of New South Wales through Regional NSW 2022. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (June 2022) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference	RDOC22/103181
Mine safety reference	SA22-01
Date published	17 June 2022
Authorised by	Chief Inspector - Office of the Chief Inspector