

WEEKLY INCIDENT SUMMARY

Week ending Friday 15 July 2022


This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance

High level summary of emerging trends and our recommendations to operators.

TYPE	NUMBER
Reportable incident total	28
Summarised incident total	3

Summarised incidents

INCIDENT TYPE	SUMMARY	COMMENTS TO INDUSTRY
Dangerous incident IncNot0042577 Underground metals mine Fire or explosion 	A tele-remote loader tripped off on low hydraulic oil. An operator went to investigate and found a small fire in the engine bay. The fire was extinguished with a hand-held extinguisher. A hydraulic hose failed and sprayed fluid onto hot engine components.	Hose management and protection is critical in preventing fires on mobile plant. Mine operators must have a system in place to identify defects and poor hose standards, assess the criticality and put controls in place to prevent a fire. Escape of fluid ignited by hot surfaces was identified as one of the top 2 causes of fires on mobile plant. For more resources, refer to our web page: Fires on mobile plant safety



Dangerous incident
IncNot0042587
Open cut coal mine
Ground or strata
failure



While a dump truck was being loaded at the toe of a highwall, material from in front of the presplit fell from the highwall and landed in the rear of the truck tray. The truck tray head-board lifted two to 3 metres and then free fell back down into the lowered position. The 2 operators in the cab were shaken and suffered minor injuries. The highwall where the failure occurred was not excavated back to the presplit wall, leaving potentially loose material hanging up on the wall. As the coal was removed below, the material in front of the presplit wall collapsed quickly. The loose material on the wall was not identified as part of the site's geotechnical hazard reports.

Mine operators must have safe systems of work in place to inspect highwalls. These inspections must consider conditions that may affect highwall stability. An assessment of the integrity of the highwall must be conducted before commencing work beneath the highwall. Loose material or overhanging rocks must be removed before any work commences or appropriate controls, such as an exclusion zone, put into place. Refer to Safety Bulletin: [SB20-01 Failure of highwalls, low walls and dumps](#).



Dangerous incident
IncNot0042593
Underground coal
mine

While lowering a roof support on a longwall recovery face, a fitter was hit in the chest by a release of fluid from a 63 mm return hose. The worker was about 1 metre from the point of failure.



Mine operators must develop and adhere to strict inspection and maintenance standards to avoid hose failures because of damaged and aged hoses.

When procedures specify the use of remotes and pendants, workers should not be entering no go zones to operate roof supports manually.

For further information refer to: [MDG-41-Fluid-power-systems](#)

Other publications of interest

The incidents are included for your review. The NSW Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

PUBLICATION	ISSUE/TOPIC
International (fatal)	
US Mine Safety and Health Administration (MSHA)	<p>On 20 June, 2022, a contract driller was working outside of his drill when he fell from the top of a highwall at 3M Little Rock.</p> <p>Details</p>
Energy Safety Canada	<p>The driver of a tank truck was unloading fluid at a production facility. The driver was found unresponsive inside the pump box of the truck with their left arm sleeve entangled in the pump shaft. After an hour and 30 minutes of resuscitation efforts by workers and emergency response personnel, the worker was declared deceased from mechanical asphyxiation.</p> <p>Details</p>
International (other, non-fatal)	
NZ MinEx	<p>An excavator operator climbed up onto his digger to check the oil as part of his prestart checks. As he climbed down from the excavator holding the handrail, the worker missed the first step and fell to the ground, landing on his back. First aid was applied, and the worker did not sustain any serious injuries.</p> <p>Details</p>
National (other, non fatal)	
Resources Safety & Health Queensland	<p>The bucket of an excavator working a double bench operation collided with the dovetail of a rear dump truck when swinging towards the truck tray. The excavator was on the lower 3.5 m high bench at the time of the incident. The impact caused a significant amount of movement to the truck and injury to the operator. The injured operator suffered a fracture to the C5 vertebrae, resulting in hospitalisation for a number of days.</p> <p>Details</p>
Worksafe Victoria	<p>WorkSafe is issuing a reminder about the importance of managing the risks associated with electrical energy while conducting surface mining and exploration activities.</p>

An air core exploration drill rig was being set up to drill a hole located within a farmer's paddock. The operator had lowered the stabilising jack legs and was in the process of raising the mast when the winching cable made contact with a 12.7kV Single-Wire Earth Return (SWER) overhead powerline. The SWER line was approximately 7 m above ground level. The drill operator suffered a shock and immediately retreated from the rig at which point the overhead line was observed. Re-exposing themselves to the electrical hazard, the operator approached the rig and activated the rig's hydraulic levers with a 'shovel' to lower the mast.

[Details](#)

Resources Safety & Health Queensland

RSHQ released Q3 incident periodical for the Queensland Coal Mines Inspectorate for recent high potential incidents. Incidents include equipment in body of water at surface mine, rock impacting excavator cabin in surface mine, rib strata failure at underground mine, serious injury at surface mine, structural failure of equipment at surface mine, dragline rigging failure at surface mine, equipment falling off jack at surface mine and a vehicle rollover at a surface mine.

[Details](#)

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through Regional NSW 2022 You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute Regional NSW as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (July 2022) and may not be accurate, current or complete. The State of New South Wales (including Regional NSW), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

DOCUMENT CONTROL

CM9 reference DOC22/199223

Mine safety reference ISR22-28

Date published 22 July 2022

Approved by Deputy Chief Inspector
Office of the Chief Inspector