

Weekly incident summary

Week ending 16 August 2024

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the NSW Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

At a glance



High level summary of emerging trends and our recommendations to operators.

| Type | Number |
|---------------------------|--------|
| Reportable incident total | 66 |
| Summarised incident total | 4 |




Summarised incidents

| Incident type | Summary | Comments to industry |
|--|--|---|
| Dangerous incident IncNot0047422 Underground coal mine | <p>While installing a conveyor belt, workers were pulling a belt winch rope over a belt structure.</p> <p>The rope, with a steel eyelet attached, was wound around the handrail of a man basket on an Eimco to assist with pulling. A knot formed in the winch rope and got caught in the V-shape return frame causing high tension on the rope.</p> <p>The rope subsequently uncoiled at speed from the basket handrail and travelled past 2 workers in the basket and the Eimco operator. The rope recoiled about 50 m past the Eimco before it stopped.</p> <p>The steel eyelet flew past the heads of 2 workers, missing them by about 300 mm.</p> | <p>This and other recent incidents of rope and sling failures while under tension are the subject of investigation and further information will be published later.</p> <p>Mine operators are reminded of the need to undertake proper risk analysis before undertaking pulling tasks.</p> <p>Workers should not be in the line of fire in the event of rope or sling failures.</p> |


Weekly incident summary week ending 16 Aug 2024

| Incident type | Summary | Comments to industry |
|---|--|---|
| |  | |
| <p data-bbox="124 972 368 1099">Dangerous incident IncNot0047473 Open cut coal mine</p> | <p data-bbox="419 972 906 1272">Workers who were removing track pins from an excavator welded a nut (M28-30) to a pin, and used a sling attached to a forklift to try to pull out the pin. The weld failed and the nut and steel shackle on the sling flew through the front window of the forklift and out the back window, hitting the operator.</p>  | <p data-bbox="943 972 1241 1010">Refer to incident above.</p> |

Weekly incident summary week ending 16 Aug 2024

| Incident type | Summary | Comments to industry |
|--|--|--|
| |  | |
| <p>Dangerous incident IncNot0047433 Underground metals mine Roads or other vehicle operating areas</p> | <p>A load haul dump (LHD) lost traction while going down a 1:4 drift and travelled for about 150 m - unable to stop. The LHD collided with the rib and conveyor structure along the way.</p>   | <p>The Resources Regulator is concerned in the increasing number of lost traction incidents.</p> <p>Operators are reminded that they must operate vehicles at a speed that is appropriate to the prevailing conditions. Engineering controls that minimise the risk of loss of control should be considered, including the use of speed-limiting devices, speed monitoring and alarms.</p> |
| <p>Dangerous incident IncNot0047438 Metals processing</p> | <p>A loaded haul truck slid on a wet surface (slight downhill gradient) and contacted the windrow. The haul road is a designated single lane area. An empty truck was waiting at the end of the single lane section which was</p> | <p>Refer to incident above.</p> |

Weekly incident summary week ending 16 Aug 2024

| Incident type | Summary | Comments to industry |
|--|--|----------------------|
| Roads or other vehicle operating areas | approximately 50 m from where the truck came to a stop. The slide was approximately 30 m.  | |

Other Resources Regulator publications

IIR24-07 Dangerous incident involving an explosion in a reclaim tunnel after use of an electrofusion welder

The Resources Regulator has published an investigation information release following a dangerous incident involving an explosion at Cadia Mine, near Orange on 22 July 2024.

The investigation will canvass the effectiveness of controls to eliminate or minimise the risks to health and safety of workers arising from the electrofusion welding process including:

- planning the work
- materials and processes used in preparing component surfaces for welding
- instruction, training, experience and supervision of the workers
- adequacy of risk assessments, work instructions and procedures
- adequacy of controls to minimise the risk of fire and explosion
- the tunnel work environment.

[Read the full report.](#)

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through the Department of Primary Industries and Regional Development 2024. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute the Department of Primary Industries and Regional Development 2024 as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (August 2024) and may not be accurate, current or complete. The State of New South Wales (including the Department of Primary Industries and Regional Development 2024), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

Weekly incident summary week ending 16 Aug 2024

| Document control | |
|-----------------------|--|
| ISSN | 2982-1010 (Online) |
| CM9 reference | RDOC24/141908 |
| Mine safety reference | ISR24-33 |
| Date published | 23 August 2024 |
| Authorised by | Director Technical Operations Mine Safety Office of the Chief Inspector |