

# Weekly incident summary

## Week ending 11 October 2024

This incident summary provides information on reportable incidents and safety advice for the NSW mining industry. To report an incident to the Resources Regulator: phone 1300 814 609 24 hours a day, 7 days a week.

### At a glance

High level summary of emerging trends and our recommendations to operators.





Type	Number
Reportable incident total	31
Summarised incident total	4

### Summarised incidents




Incident type	Summary	Comments to industry
Dangerous incident IncNot0047788 Underground coal mine Ground or strata failure	<p>A large rib fall of about 5 m long x 3.1 m high x 1.2 m deep occurred when cutting in a herringbone mains panel.</p> <p>No one was present on the side of the continuous miner where the fall occurred, although a worker was on the opposite side platform.</p> <p>It did not appear to be a lubricated fault (greasy back). Rib support consisted of 1.2 m bolts at about 2.2 - 2.4 m above the floor.</p>	<p>When mining in an inferred area of geological disturbance strata, trigger action response plans (TARPs) are to be used as a proactive tool.</p> <p>That is, support should increase for both roof, and ribs. Cut-out distances should be adhered to for a higher-level TARP.</p>



## Weekly incident summary week ending 11 October 2024

Incident type	Summary	Comments to industry
<p data-bbox="124 589 371 797">           Dangerous incident            IncNot0047811            Underground coal mine            Fire or explosion         </p> 	 <p data-bbox="416 589 898 808">           Heating occurred on an underground conveyor from a failed roller. While undertaking conveyor inspections, a deputy smelt something burning and found 2 x 5 mm glowing embers under the belt.         </p> <p data-bbox="416 831 927 976">           The roller bearings had catastrophically failed, allowing the roller shell to run on the shaft, creating excessive friction and heat.         </p> 	<p data-bbox="954 589 1469 958">           Mine operators must have systems to identify and change-out defective conveyor rollers. Workers conducting conveyor inspections must be aware of the increased risk of roller failure at high tension areas of conveyors. They must also diligently inspect for fire risks such as accumulation of material, failing or collapsed idlers and contact between conveyor belts and fixed structures.         </p>
<p data-bbox="124 1397 371 1648">           Dangerous incident            IncNot0047797            Open cut coal mine            Roads or other vehicle operating areas         </p> 	<p data-bbox="416 1397 922 1585">           A loaded haul truck exceeded its retard window while descending an 8% ramp. The truck reached a speed of 60 kph before the operator made an emergency application of the service brake.         </p> <p data-bbox="416 1608 898 1753">           The truck stopped within an estimated distance of 300 m. A working wheel dozer was positioned about 30-40 m from where the haul truck stopped.         </p>	<p data-bbox="954 1397 1437 1507">           When operating machinery, a worker's primary focus must remain on the operation and control of the vehicle.         </p> <p data-bbox="954 1529 1437 1675">           Excessive speeds can easily result in a fatality. All vehicle operators are required to adhere to the mine's road rules.         </p> <p data-bbox="954 1697 1437 1877">           Mine operators should review the triggers for competency assessment and the minimum level of competence required before workers are authorised for solo operations.         </p>

# Weekly incident summary week ending 11 October 2024

Incident type	Summary	Comments to industry
		
<p>Dangerous incident IncNot0047789 Open cut coal mine Roads or other vehicle operating areas</p> 	<p>An articulated truck rolled its dump body while negotiating a bend. The cabin remained upright, and no one was injured.</p> 	<p>Articulated truck rollovers continue to be a cause for concern on mine sites. The stability of articulated vehicles is a known risk that needs to be managed.</p> <p>When operating articulated equipment workers must drive at appropriate speeds, particularly when negotiating corners and turning the machine around.</p>

## Other Resources Regulator publications

### Report released following fatality at Austar Coal Mine

An investigation information release has been published by the Resources Regulator following an incident where a contract worker was fatally injured when he fell through a mine shaft on 17 September 2024.

The incident occurred when contractors were preparing to attach steel plates to beams fixed to a shaft cover at the Austar Coal Mine’s number 2 shaft. When the incident occurred, the mine was in a decommissioning phase and was being prepared for closure.

The mine is approximately 10 kilometres from Cessnock, in the NSW Hunter Valley.

The Investigation Information Release describes the initial investigations conducted by the Regulator into the cause and circumstances of the incident and provides safety information to industry. The mine operator and other parties are assisting with further investigations, and a report will be published when the investigation is concluded.

Read the [investigation information release](#)

### Safety alert SA24-04 Haul truck rear strut injures worker

A swinging load hit a worker, resulting in injuries including a serious laceration to a leg. Other incidents of a similar nature where hydraulic cylinders, suspension or driveline components have not

## Weekly incident summary week ending 11 October 2024

been appropriately restrained, and have fallen, swung or slid, have occurred recently resulting in serious injuries or placing workers at risk.

Read the [safety alert](#)

### Other publications of interest

The incidents are included for your review. The Resources Regulator does not endorse the findings or recommendations of these incidents. It is your legal duty to exercise due diligence to ensure the business complies with its work health and safety obligations.

Publication	Issue/topic
	<b>International (fatal)</b>
MSHA	<p>On May 31, 2024, a 27-year-old roof bolter with over 3 years of mining experience, died when a portion of a mine roof fell on him. The incident occurred as he was traveling on foot through an area of unsupported roof. The accident occurred because the operator did not ensure that all miners were working or traveling under supported roof.</p> <p><a href="#">Details</a></p>
MSHA	<p>On September 20, 2024, a miner died after he fell from a front-end loader while attempting to replace a bulb on the right front headlight.</p> <p>Best practices:</p> <ul style="list-style-type: none"><li>• Develop and implement a safety program for surface mobile equipment that includes actions taken to identify hazards and risks to reduce accidents, injuries, and fatalities related to surface mobile equipment.</li><li>• Identify hazards and risks.</li><li>• Take corrective actions to eliminate/reduce risks.</li><li>• Provide and maintain safe access to all workplaces and establish safe work procedures.</li></ul> <p><a href="#">Details</a></p>

Note: While the majority of incidents are reported and recorded within a week of the event, some are notified outside this time period. The incidents in this report therefore have not necessarily occurred in a one-week period. All newly recorded incidents, whatever the incident date, are reviewed by the Chief Inspector and senior staff each week. For more comprehensive statistical data refer to our annual performance measures reports.

© State of New South Wales through the Department of Primary Industries and Regional Development 2024. You may copy, distribute, display, download and otherwise freely deal with this publication for any purpose, provided that you attribute the Department of Primary Industries and Regional Development 2024 as the owner. However, you must obtain permission if you wish to charge others for access to the publication (other than at cost); include the publication in advertising or a product for sale; modify the publication; or republish the publication on a website. You may freely link to the publication on a departmental website.

Disclaimer: The information contained in this publication is based on knowledge and understanding at the time of writing (October 2024) and may not be accurate, current or complete. The State of New South Wales (including the Department of Primary Industries and Regional Development 2024), the author and the publisher take no responsibility, and will accept no liability, for the accuracy, currency, reliability or correctness of any information included in the document (including material provided by third parties). Readers should make their own inquiries and rely on their own advice when making decisions related to material contained in this publication.

## Weekly incident summary week ending 11 October 2024

Document control	
ISSN:	2982-1010 (online)
CM9 reference	RDOC24/191178
Mine safety reference	ISR24-xx
Date published	18 October 2024
Authorised by	Deputy Chief Inspector Office of the Chief Inspector